

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
1	Apple iPhone 6	E	✓	0-07-0258-0.08	9.3.3 (13G34)
2	Apple iPhone 6s	E	✓	0-07-0258-0.08	9.3.3 (13G34)
3	Apple iPhone 6 Plus	A'	✓	0-07-0258-0.08	9.3.3 (13G34)
4	Apple iPhone 6s Plus	A'	✓	0-07-0258-0.08	10.0.1 (14A403)
5	Apple iPhone 7	E	✓	0-07-0258-0.08	10.0.3 (14A551)
6	Apple iPhone 7 Plus	A'	✓	0-07-0258-0.08	10.0.3 (14A551)
7	Apple iPhone 8	E	✓	0-07-0258-0.08	11.0.3 (15A432)
8	Apple iPhone 8 Plus	A'	✓	0-07-0258-0.08	11.0.3 (15A432)
9	Apple iPhone X	A'	✓	0-07-0258-0.08	11.1.1 (15B150)
10	Apple iPhone XS Max	A'	✓	0-07-0258-0.08	13.2.3 (17B111)
11	Apple iPhone 11	A'	✓	0-07-0258-0.08	13.1.2 (17A860)
12	Apple iPhone 11 Pro	A'	✓	0-07-0258-0.08	13.3.1 (17D50)
13	Apple iPhone 11 Pro Max	A'	✓	0-07-0258-0.08	13.3.1 (17D50)
14	Apple iPhone 12	A'	✓	0-07-0258-0.08	14.3 (18C66)
15	Apple iPhone 12 mini	E	✓	0-07-0258-0.08	14.2.1 ((18B121)
16	Apple iPhone 12 Pro	A'	✓	0-07-0258-0.08	14.3 (18C66)
17	Apple iPhone 12 Pro Max	A'	✓	0-07-0258-0.08	14.3 (18C66)
18	BlackBerry Leap (STR100-1)	A'	✓	0-07-0258-0.01	BB OS 10.3.2.2836
19	BlackBerry Priv STV100-4	A'	✓	0-07-0258-0.01	Android 6.0.1 AAF518
20	BlackBerry Q20 Classic	E	✓	0-07-0258-0.01	BB OS v10.3.2.2836
21	BlackBerry Z10	E	✓	0-07-0258-0.01	BB OS v10.3.2.2836
22	BlackBerry Z30	A'	✓	0-07-0258-0.01	BB OS v10.3.2.2836
23	Google Pixel 2 XL	A'	✓	07-0257-0F.01	Android 8.1.0 OPM2.171026.006.C1
24	HTC Desire 310	E	✓	0-07-0258-0.01	Android OS 4.2.2 sw. Nr. 1.00.118.4
25	HTC One	E	✓	0-07-0258-0.01	Android 4.2.2 4.20.111.21
26	HTC One M9	A'	✓	0-07-0258-0.01	Android 6.0 3.35.111.14
27	HTC ONE mini	E			Android 4.0.3 2.22.111.1
28	HTC One Max	A'	✓	0-07-0258-0.01	Android 5.0.2 4.14.111.11
29	HTC U11	A'			Android 7.1.1 1.27.401.11
30	HTC Windows Phone 8X	E	✓	0-07-0258-0.01	Win8 Radio sw:1.20b.32.19.04_15.67b.32.19
31	HUAWEI Ascend P1 U9200	A'	✓	0-07-0258-0.01	Android 4.0.3 U9200-1V100R001C00B219
32	HUAWEI Mate 8 (NXT-L29)	A'	✓	0-07-0258-0.01	Android 6.0 NXT-L29C432B192
33	HUAWEI Mate 9 (MHA-L29)	A'			Android 7.0 MHA-L29C432B156
34	HUAWEI Mate 10 Pro (BLA-L29)	A'	✓	07-0257-0F.01	Android 8.0.0 BLA-L29 8.0.0.142(C432)
35	HUAWEI P9 (EVA-L09)	A'			Android 6.0 EVA-L09C432B170
36	HUAWEI P9 Lite (VNS-L21)	A'	✓	0-07-0258-0.01	Android 6.0 VNS-L21C432B160
37	HUAWEI P10 (VTR-L29)	A'			Android 7.0 VTR-L29C432B112

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
38	HUAWEI P10 Plus (VKY-L29)	A'			Android 7.0 VKY-L29C432B150
39	LG E960 Nexus 4	E	✓	0-07-0258-0.01	Android 5.1.1 LMY48T
40	LG Nexus 5	E	✓	0-07-0258-0.01	Android 6.0.1 MOB30M
41	LG Nexus 5X	A'			Android 7.0 NRD90R
42	LG G2 D802	E	✓	0-07-0258-0.01	Android 4.4.2 KOT49L.D80220d
43	LG G3 (D855)	A'	✓	0-07-0258-0.01	Android 5.0 V21a-260-01
44	LG G4 (H815)	A'	✓	0-07-0258-0.01	Android 6.0 V20d-260-02
45	LG G5 (H850)	A'			Android 6.0.1 10d-EUR-XX
46	LG G6 (H870)	A'			Android 7.0 V10f-EUR-XX
47	LG G Flex (D955)	A'	✓	0-07-0258-0.01	Android 4.4.2 KOT49L.D95520b
48	LG P760 Optimus L9	E	✓	0-07-0258-0.01	Android 4.1.2 P76020h-EUR-XX
49	LG P880 Optimus 4X HD	E	✓	0-07-0258-0.01	Android 4.1.2 SW LG-P88020b-232-10
50	LG V10 (H961N)	A'	✓	0-07-0258-0.01	Android 5.1.1 SW V10c-SEA-XX
51	LG X power (K220)	A'	✓	0-07-0258-0.01	Android 6.0.1 SW V10a-EUR_XX
52	Microsoft Lumia 535	A'	✓	0-07-0258-0.01	WP 8.1 Update 02074.00000.15234.28006
53	Microsoft Lumia 950	A'			Win10 Mobile 01078.00038.16025.39025
54	Motorola Nexus 6	A'	✓	0-07-0258-0.01	Android 6.0.1 MOB30M
55	Nokia 6 (TA-1021)	A'	✓	0-07-0258-0.01	Android 7.1.2 00WW_3_700
56	Nokia 8	A'			Android 7.1.1 00WW_3_09A
57	Nokia Lumia 625	E	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw:3.2.28060.7
58	Nokia Lumia 635	E	✓	0-07-0258-0.01	Win 8.1 Update Radio sw:201c1.00401.0001
59	Nokia Lumia 900	E	✓	0-07-0258-0.01	Windows Phone 7.5 Radio sw:2.1.75.25
60	Nokia Lumia 920	E	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw:1.0.202158.3
61	Nokia Lumia 925	E	✓	0-07-0258-0.01	Windows Phone 8.0 Radio sw:3.2.04033.1
62	Nokia Lumia 930	E	✓	0-07-0258-0.01	Win8.1 Update 02540.00019.14484.37006
63	Nokia Lumia 909/1020	F	✓	0-07-0258-0.01	Win 8.1 Update 3051.50009.1451.1010
64	Nokia Lumia 909/1020	A'	✓	0-07-0258-0.01	Win 8.1 Update SW 02540.00019.15235.40004
65	OnePlus 2 (ONE A2003)	A'			Android 6.0.1 ONE A2003_24_16122
66	Samsung A510F Galaxy A5 (2016)	A'	✓	0-07-0258-0.01	Android 5.1.1 LMY47X.A510FXXS2APE2
67	Samsung A520F Galaxy A5 (2017)	A'			Android 6.0.1 sw MMB29K.A520FXXU1A1PLP
68	Samsung G900F Galaxy S5	A'	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G900FXXU1CPPEM
69	Samsung G903F Galaxy S5 Neo	A'	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G903FXXU1BPF4
70	Samsung G920F Galaxy S6	A'	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G920FXXU3DPFB
71	Samsung G925F Galaxy S6 edge	A'	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G925FXXU3DPCA
72	Samsung G930F Galaxy S7	E	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G930FXXU1A1PEQ
73	Samsung G935F Galaxy S7 edge	A'	✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G935FXXU1APD1

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

No	Phone	Set of tips	Charger available	Article code (Charger)	Version of phone software used to test/ Comments
74	Samsung G950F Galaxy S8	E			Android 7.0 NRD90M.G950FXXU1AQDG
75	Samsung G955F Galaxy S8+	A'			Android 7.0 NRD90M.G955FXXU1AQDG
76	Samsung G973F Galaxy S10	A'			Android 9 PPR1.180610.011.G973FXXU1ASD5
77	Samsung I8750 Ativ S	A'	✓	0-07-0258-0.01	Windows Phone 8.1 Update 2424.15.3.2
78	Samsung I9300 Galaxy S III	E	✓	0-07-0258-0.01	Android 4.3 JSS15J.I9300XXUGNG3
79	Samsung I9305 Galaxy S III Lte	E	✓	0-07-0258-0.01	Android 4.3 JSS15J.I9300XXUGNG3
80	Samsung I9505 Galaxy S4	E	✓	0-07-0258-0.01	Android 4.4.2 I9505XXUFNB8
81	Samsung J320F Galaxy J3 (2016)	E	✓	0-07-0258-0.01	Android 5.1.1 LMY47V.J320FXXS0AQ1
82	Samsung J510FN Galaxy J5 (2016)	A'	✓	0-07-0258-0.01	Android 6.0.1 sw MMB29M.J510FNXXU2APK6
83	Samsung N7000 Galaxy Note	A'	✓	0-07-0258-0.01	Android 4.1.2 JZO54K.N7000XXLT4
84	Samsung N9005 Galaxy Note 3	A'	✓	0-07-0258-0.01	Android 5.0 LRX21V.N9005XXUGBOK6
85	Samsung N910F Galaxy Note 4	A'	✓	0-07-0258-0.01	Android 6.0.1 MMB29M.N910FXXU1DPI1
86	Samsung N915FY Galaxy Note Edge	A'	✓	0-07-0258-0.01	Android 6.0.1 MMB29M.N915FYXXS1DPI1
87	Samsung N950F Galaxy Note 8	A'			Android 7.1.1 NMF26X.N950FXXU1AQI1
88	SONY Xperia S (LT26)	E	✓	0-07-0258-0.01	Android 4.1.2 6.2.B.1.96
89	SONY Xperia SP (C5303)	E	✓	0-07-0258-0.01	Android 4.3 sw 12.1.A.1.201
90	SONY Xperia X Performance (F8131)	A'	✓	0-07-0258-0.01	Android 7.1.1 sw 41.2.A.7.53
91	SONY Xperia XZ (F8331)	A'			Android 7.0 sw 39.2.A.0.417
92	SONY Xperia XZ Premium (G8142)	A'			Android 7.1.1 sw 45.0.A.7.120
93	SONY Xperia Z3 (D6603)	A'	✓	0-07-0258-0.01	Android 5.1.1 sw 23.4.A.1.264
94	SONY Xperia Z3+ (C6553)	A'	✓	0-07-0258-0.01	Android 6.0.1 sw 32.2.A.0.305
95	SONY Xperia Z3 Compact (D5803)	E			Android 6.0.1 sw 23.5.A.1.291
96	SONY Xperia Z5 (E6653)	A'	✓	0-07-0258-0.01	Android 6.0.1 sw 32.2.A.0.253
97	Xiaomi Mi 5	A'			Android 6.0.1 MXB48T MIUI Global 8.1

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call), E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.