

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
1	Apple iPhone	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓						✓	0-07-0258-0.07	3.0 (7A341)
2	Apple iPhone 3G	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.07	4.2.1 (8C148)
3	Apple iPhone 3GS	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.07	6.1.3 (10B329)
4	Apple iPhone 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.07	7.0.4 (11B554a)
5	Apple iPhone 4S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.07	7.0.4 (11B554a)
6	Apple iPhone 5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	8.1 (12B411)
7	Apple iPhone 5c	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	8.1 (12B411)
8	Apple iPhone 5s	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	8.1 (12B411)
9	Apple iPhone 6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	8.0.2 (12A405)
10	Apple iPhone 6s	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	10.0.1 (14A403)
11	Apple iPhone 6 Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	8.0.2 (12A405)
12	Apple iPhone 6s Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	9.1 (13B143)
13	Apple iPhone 7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	10.0.3 (14A551)
14	Apple iPhone 7 Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	10.0.3 (14A551)
15	Apple iPhone 8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	11.0.3 (15A432)
16	Apple iPhone 8 Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	11.0.3 (15A432)
17	Apple iPhone SE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	9.3.2 (13F69)
18	Apple iPhone X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	11.1.2 (15B202)
19	Apple iPhone 11	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓					✓	✓	0-07-0258-0.08	13.1.2 (17A860)
20	ASUS Solaris V1520	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.02	5.2.1620(Build 18125.0.4.2)
21	BlackBerry 8110 Pearl	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓						✓	✓	0-07-0258-0.02	V4.5.0.55
22	BlackBerry 8220 Pearl Flip	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓						✓	✓	0-07-0258-0.01	v4.6.0.94
23	BlackBerry 8300 Curve	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓						✓	✓	0-07-0258-0.02	V4.5.0.182
24	BlackBerry 8310	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓ ²	✓	✓	✓	0-07-0258-0.02	V4.5.0.180
25	BlackBerry 8520 Curve	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓						✓	✓	0-07-0258-0.01	V4.6.1.286 Pl 4.2.0.122
26	BlackBerry 8800	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓						✓	✓	0-07-0258-0.02	V4.5.1174
27	BlackBerry 9000 Bold	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓						✓	✓	0-07-0258-0.02	V4.6.0.40
28	BlackBerry 9100 Pearl	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓ ²	✓	✓	✓	0-07-0258-0.01	v5.0.0.696 (Platform 6.2.0.57)

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone

✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
29	BlackBerry 9105 Pearl	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓ ²	✓	✓	✓	0-07-0258-0.01	v5.0.0.696 (Platform 6.2.0.57)	
30	BlackBerry 9320 Curve	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.1.0.398 (Platform 9.49.0.31)	
31	BlackBerry 9360 Curve	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.1.0..234 (Platform 9.16.0.57)	
32	BlackBerry 9380 Curve	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.1.0.470 (Platform 9.32.0.108)	
33	BlackBerry 9500 Storm	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓ ²	✓	✓	✓	0-07-0258-0.01	v4.7.0.41 PI 4.0.0.40	
34	BlackBerry 9520 Storm2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓ ²	✓	✓	✓	0-07-0258-0.01	V5.0.0.497 PI 4.2.0.220	
35	BlackBerry 9700 Bold	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v5.0.0.979 PI 5.1.0.178	
36	BlackBerry 9780 Bold	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v6.0.0.668 PI 6.6.0.236	
37	BlackBerry 9790 Bold	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.0.0.528	
38	BlackBerry 9800 Torch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v6.0.0.534 PI 6.6.0.200	
39	BlackBerry 9810 Torch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.1.0.342 PI 5.4.0.276	
40	BlackBerry 9860 Torch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓ ²	✓	✓	✓	0-07-0258-0.01	V7.1.0.746	
41	BlackBerry 9900 Bold Touch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v7.0.0.585 (Platform 5.0.0.734)	
42	BlackBerry Leap (STR100-1)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	BB OS 10.3.2.2836	
43	BlackBerry Passport (SQW100-1)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	BB OS 10.3.2.2836	
44	BlackBerry Priv STV100-4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		Android 6.0.1 AAF518	
45	BlackBerry Q5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v10.2.0.429	
46	BlackBerry Q10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v10.2.1.537	
47	BlackBerry Q20 Classic	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v10.3.2.2836	
48	BlackBerry Z10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	v10.2.0.429	
49	BlackBerry Z30	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	10.2.1.3062	
50	CAT (Caterpillar) B15	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		Android 4.1.2 1375548110	
51	HTC 7 Mozart	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win7.5 Radio5.71.09.02a_22.51.50.21U	
52	HTC 7 Pro	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 7.5 Radio 5.71.09.02a_22.51.50.21U	
53	HTC Desire	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 2.2.2 sw. Nr. 2.29.110.6	
54	HTC Desire HD	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 2.3.5 sw. Nr. 3.12.405.1	
55	HTC Desire S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 2.3.5 2.10.401.8	
56	HTC Desire X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android OS 4.1.1 sw. Nr. 2.23.118.2	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone

✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
57	HTC Desire Z	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android OS 2.3.3 sw. Nr. 2.42.405.4
58	HTC Desire 310	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android OS 4.2.2 sw. Nr. 1.00.118.4
59	HTC EVO 3D X515m	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android OS 4.0.3 sw. Nr. 3.28.401.1
60	HTC Incredible S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android OS 4.0.4 sw. Nr. 4.10.405.1
61	HTC Legend	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	FW: 2.2 sw. Nr. 3.14.161.1
62	HTC Hero / T-Mobile G2 Touch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.02	Android 2.1-update1 3.31.111.1
63	HTC Magic	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.02	Android 1.5 CRB43
64	HTC One	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 4.3 3.63.111.3
65	HTC One M8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 4.4.3 2.22.401.5
66	HTC One M9	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 6.0 3.35.111.14
67	HTC One Max	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 4.4.2 3.18.111.3
68	HTC ONE mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 4.4.2 3.10.401.6
69	HTC One S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 4.1.1 3.16.111.10
70	HTC One V	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 4.0.3 sw. Nr. 2.22.111.1
71	HTC One X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 4.0.4 sw. Nr. 2.17.401.2
72	HTC Sensation	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android OS 4.0.3 sw. Nr. 3.33.111.51
73	HTC Tattoo	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.02	Android 1.6 SW 1.67.405.70
74	HTC Touch Diamond	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.02	Windows Mobile 6.1 OS 5.2.19965
75	HTC Touch DIAMOND 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.02	Windows Mobile 6.5 OS 5.2.21887
76	HTC Touch	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.02	Windows Mobile 6 OS 5.2.1238
77	HTC Touch2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.02	Windows Mobile 6.5 OS 5.2.21854
78	HTC Touch Cruise	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.02	3.13.407.0 GER
79	HTC Touch Dual	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.02	1.31.407.09
80	HTC Touch HD	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.02	ROM: 1.56.407.2 (43972) GER
81	HTC HD mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	ROM: 1.07.407.1 (85429) GER
82	HTC HD2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	1.43.111.2 (70315) GER
83	HTC HD7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓	✓	✓	0-07-0258-0.01	Win7.5 Radio sw:5.71.09.02a_22.51.50.21U
84	HTC Touch Pro	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.02	19960.1.2.2

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

- ✓ working
- ✓¹ only from phone
- ✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
85	HTC TyTN II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.02	3.28.405.0 WWE Radio 1.65.16.25
86	HTC U11	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 8.0.0 2.33.401.10
87	HTC Wildfire	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 2.2.1 2.24.162.1
88	HTC Windows Phone 8X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Win 8 Radio sw:1.17b.32.19.14_15.52b.32.19
89	HTC S730	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.02	CE OS 5.2.1622 (Build 18128.0.4)
90	HUAWEI Ascend P1 U9200	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	Android 4.0.3 U9200-1V100R001C00B219
91	HUAWEI G8 or GX8 (RIO-L01)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 5.1 RIO-L01C432B180
92	HUAWEI Mate 8 (NXT-L29)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 6.0 NXT-L29C432B192
93	HUAWEI Mate 9 (MHA-L29)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 7.0 MHA-L29C432B156
94	HUAWEI Mate 10 Pro (BLA-L29)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 8.0.0 BLA-L29 8.0.0.142(C432)
95	HUAWEI P8 (GRA-L9)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 5.0 GRA-L09V100R001C900B151
96	HUAWEI P8 lite (ALE-L21)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 5.0.1 EMUI 3.1
97	HUAWEI P9 (EVA-L09)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 6.0 EVA-L09C432B170
98	HUAWEI P9 Lite (VNS-L21)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 6.0 VNS-L21C432B160
99	HUAWEI P10 (VTR-L29)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 7.0 VTR-L29C432B112
100	HUAWEI P10 Plus (VKY-L29)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 7.0 VKY-L29C432B150
101	LG BL20 New Chocolate	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	BL20 V10j
102	LG BL40 New Chocolate	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	BL40-MSM76XX-V10b-NOV-06-2009-DE
103	LG E960 Nexus 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.2 KOT49H
104	LG Nexus 5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.4 KTU84P
105	LG Nexus 5X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓								Android 7.0 NRD90R
106	LG G2 D802	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 4.2.2 D80210a-262-01
107	LG G2 mini LTE (D620r)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 4.4.2 V10c-260-01
108	LG G3 (D855)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 4.4.2 V10i-260-01
109	LG G4 (H815)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 6.0 V20d-260-02
110	LG G5 (H850)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 6.0.1 V10d-EUR-XX
111	LG G6 (H870)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01	Android 7.0 V10f-EUR-XX
112	LG G Flex (D955)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.2 D95520a-262-02

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments	
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)		
113	LG GT500	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓						✓	0-07-0258-0.01	GT500-10i	
114	LG KF 750 Secret	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓			✓	✓							KF750-V10a-24042008
115	LG KM 900 Arena	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓									KM900AT_V10t
116	LG P710 Optimus L7 II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 4.1.2 SW LG-P71010e-EUR-XX		
117	LG P760 Optimus L9	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 4.1.2 SW LG-P76020h-EUR-XX		
118	LG P880 Optimus 4X HD	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 4.1.2 SW LG-P88020b-232-10		
119	LG Optimus 2X (P990 Optimus Speed)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 2.3.4 SW LGE LGP990-V20e		
120	LG V10 (H961N)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓						Android 5.1.1 SW V10c-SEA-XX
121	LG X power (K220)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓						Android 6.0.1 SW V10a-EUR_XX
122	Microsoft Lumia 532 Dual SIM	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Win8.1 Update SW 20c9.00076.0001		
123	Microsoft Lumia 535	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Win8.1 Update SW 20c9.00076.0001		
124	Microsoft Lumia 535 Dual SIM	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Win8.1 Update SW 20c9.00076.0001		
125	Microsoft Lumia 550	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Win10 Mobile SW 01078.00037.16082.41022		
126	Microsoft Lumia 640 Dual SIM	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Win8.1 Update 2 SW 20c9.00072.0001		
127	Microsoft Lumia 640 XL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Win8.1 Update 2 SW 401c3.00009.0001		
128	Microsoft Lumia 650	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Win10 Mobile SW 01078.00037.16082.41010		
129	Microsoft Lumia 950	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	07-0257-0F.01	Win10 Mobile SW 01078.00038.16025.39025		
130	Microsoft Lumia 950 XL	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓						Win10 Mobile SW 01078.00038.16082.36021
131	Motorola DEFY (MB525)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 2.2.2 JOREM_U33.4.2_179-6.1		
132	Motorola DEFY+ (MB526)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓	✓					Android 2.3.6 4.5.1-134_DFP-231
133	Motorola Milestone	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 2.2.1 NK: SHOLS_U2_05.26.0		
134	Motorola Milestone 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓	✓					Android 2.2 NK: MILS2_U6_4.1-22
135	Motorola Motoluxe (XT615)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 2.3.7 NK: 1_67C_4035		
136	Motorola Nexus 6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android 6.0.1 NK: MOB31E		
137	Motorola RAZR i XT890	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	0-07-0258-0.01	Android4.1.2 9.8.21-50_SMI-26.1358455837		
138	Motorola RAZR XT910	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓						Android 4.0.4 6.7.2-180_SPU-19-TA-11.6
139	Nokia 6 (TA-1021)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓						Android 7.1.1 00WW_3_24A_SP03
140	Nokia 8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓			✓		✓	07-0257-0F.01	Android 7.1.1 00WW_3_09A		

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
141	Nokia 113	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.04	V 03.24
142	Nokia 208.1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	V 06.01
143	Nokia 500	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Symbian Belle Refresh 111.021.0028
144	Nokia 515	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	V 07.01
145	Nokia 5230	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-10-04-0069-0	V 51.0.002
146	Nokia 5530 XpressMusic	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-10-04-0069-0	V 11.0.054
147	Nokia 6210 Navigator	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-10-04-0069-0	V 05.16
148	Nokia 6300	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓			✓		✓	0-10-04-0069-0	V07.30
149	Nokia 6500c	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓			V09.48
150	Nokia 6600i Slide	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	V 36.16
151	Nokia 6700 classic	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	V 13.21
152	Nokia Asha 300	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	V07.65
153	Nokia Asha 311	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	V07.36.0.0
154	Nokia C3-01 Touch and Type	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	V 07.15
155	Nokia C5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	V 073.001
156	Nokia C5-03	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	V 23.0.015
157	Nokia C6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-10-04-0069-0	V 42.0.004
158	Nokia C7-00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	Nokia Belle Refresh 111.040.1511
159	Nokia E5-00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓		✓	0-10-04-0069-0	V 081.004
160	Nokia E6-00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	Nokia Belle Refresh 111.140.0058
161	Nokia E7-00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-10-04-0069-0	Symbian Belle 111.030.0609
162	Nokia E51	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-10-04-0069-0	V411.34.001
163	Nokia E52	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	033.002
164	Nokia E55	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	022.009
165	Nokia E66	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-10-04-0069-0	501.21.001
166	Nokia E71	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-10-04-0069-0	500.21.009
167	Nokia E72	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	0-07-0258-0.01	091.003
168	Nokia Lumia 520	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓	✓	0-07-0258-0.01	Win 8.0 SW 2.0.242020.8

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone

✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
169	Nokia Lumia 610	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 7.8 Radio sw:1.0.66.00	
170	Nokia Lumia 625	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 8.0 Radio sw:3.2.28060.7	
171	Nokia Lumia 635	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 8.1 Radio sw:201c1.00401.0001	
172	Nokia Lumia 800	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 7.5 Radio sw:7.10.8107.79	
173	Nokia Lumia 820	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 8.0 sw: 1.0.202132.3	
174	Nokia Lumia 920	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 8.0 sw: 1.0.202132.3	
175	Nokia Lumia 925	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 8.0 Radio sw:3.2.04033.1	
176	Nokia Lumia 930	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win8.1Radio sw:201c110.00039.0001	
177	Nokia Lumia 1020 (909)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win 8.0 Radio sw:3.2.04047.1	
178	Nokia Lumia 1520	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Win8.1SW 02540.00019.15235.40004	
179	Nokia N8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Nokia Belle Refresh 111.040.1511	
180	Nokia N9	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	V 40.2012.21-3.342.01.1_PR_342	
181	Nokia N900	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	V 21.2011.38-1	
182	Nokia X6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-10-04-0069-0	V 40.0.002	
183	Nokia X7-00	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	V 111.040.1511	
184	OnePlus 2 (ONE A2003)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		Android 6.0.1 ONE A2003_24_161227	
185	RugGear LM802B	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		78	
186	RugGear P860 Explorer	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	78	
187	Samsung A510F Galaxy A5 (2016)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 5.1.1 swLMY47X.A510FXXS2APE2	
188	Samsung A520F Galaxy A5 (2017)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	07-0257-0F.01	Android 6.0.1 sw MMB29K.A520FXXU1A1PLP	
189	Samsung Ace S5830	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 2.3.6 sw S5830XWKTU	
190	Samsung B550H Xcover 550	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	B550HXUAOE6	
191	Samsung B2700	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		B2700XXIB2	
192	Samsung E2121B	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		E2121BXXKC1	
193	Samsung G386F Galaxy Core LTE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.2.2 JDQ39.G386FXXUANB4	
194	Samsung G388F Galaxy Xcover 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.4.4 KTU84P.G388FXXU1AOG4	
195	Samsung G800F Galaxy S5 mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	Android 4.4.2 KOT49H.G800FXXU1ANJ2	
196	Samsung G900F Galaxy S5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		Android 4.4.2 KOT49H.G900FXXU1ANCE	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments	
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)		
197	Samsung G903F Galaxy S5 Neo	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 6.0.1 MMB29K.G903FXXU1BPF4	
198	Samsung G920F Galaxy S6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓								Android 5.0.2 LRX22G.G920FXXU1AOCV
199	Samsung G925F Galaxy S6 edge	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓								Android 5.0.2 LRX22G.G925FXXU1AOCV
200	Samsung G930F Galaxy S7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓								Android 6.0.1 MMB29K.G930FXXU1APC8
201	Samsung G935F Galaxy S7 edge	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓								Android 6.0.1 MMB29K.G935FXXU1APC8
202	Samsung G950F Galaxy S8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓								Android 7.0 NRD90M.G950FXXU1AQDG
203	Samsung G955F Galaxy S8+	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓								Android 7.0 NRD90M.G955FXXU1AQDG
204	Samsung G973F Galaxy S10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓								Android9 PPR1.180610.011.G973FXXU1ASD5
205	Samsung G7105 Galaxy Grand 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓					✓	0-07-0258-0.01	Android 4.3 JLS36C.G7105XXUANF4	
206	Samsung I8000 Omnia II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓								I8000XXII6
207	Samsung I8150 Galaxy W	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓					✓	0-07-0258-0.01	Android 2.3.6 I8150XXLMI	
208	Samsung I8160 Galaxy Ace 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓					✓	0-07-0258-0.01	I8160XXLI2	
209	Samsung I8190 Galaxy S III mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓					✓	0-07-0258-0.01	Android 4.1.2 I8190XXAMG4	
210	Samsung i8320 Vodafone 360 H1	✓	✓		✓	✓			✓	✓	✓	✓	✓ ¹				✓								✓	0-07-0258-0.01	i8320BUIK1
211	Samsung I8700 Omnia 7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓	✓						✓	0-07-0258-0.01	Win 7.5 Radio sw:2424.11.9.1
212	Samsung I8750 Ativ S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓	✓						✓	0-07-0258-0.01	Win 8.0 Radio sw: 2424.13.5.1
213	Samsung i8910 Omnia HD	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓	✓						✓	0-07-0258-0.01	I8910XXJA2
214	Samsung I9000 Galaxy S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 2.3.6 I9000BOJW6
215	Samsung I9001 Galaxy S Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 2.3.6 I9001XXKPK
216	Samsung I9100 Galaxy S II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 4.1.2 I9100XXWLS
217	Samsung I9195 Galaxy S 4 mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 4.2.2 I9195XXUBMJ7
218	Samsung I9300 Galaxy S III	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 4.1.2 sw: I9300XXAMG4
219	Samsung I9305 Galaxy S III Lte	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 4.4.4 KTU84P.I9305XXUFOA1
220	Samsung I9505 Galaxy S4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓								Android 4.3 sw: JSS15J.I9505XXUEMKF
221	Samsung J320F Galaxy J3 (2016)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 5.1.1 LMY47V.J320FXXS0AQA1
222	Samsung J510FN Galaxy J5 (2016)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android6.0.1 sw MMB29M.J510FNXXU2APK6
223	Samsung N7000 Galaxy Note	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 4.1.2 sw: N7000XXLT4
224	Samsung N7100 Galaxy Note II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	Android 4.1.2 sw: N7100XXDME6

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments	
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)		
225	Samsung N9005 Galaxy Note 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓			Android 4.3 JSS15J.N9005XXUDMJ7	
226	Samsung N910F Galaxy Note 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓				Android 6.0.1 MMB29M.N910FXXU1DPI1	
227	Samsung N915FY Galaxy Note Edge	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 6.0.1 MMB29M.N915FYXS1DPI1	
228	Samsung N950F Galaxy Note 8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	07-0257-0F.01		Android 7.1.1 NMF26X.N950FXXU1AQI1	
229	Samsung S3650 Corby	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓				✓				S3650XXII3	
230	Samsung S5260 Star II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		S5260XXKC4	
231	Samsung S5360 Galaxy Y	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		Android 2.3.6 sw: S5360XXMK1	
232	Samsung S5570i Galaxy Mini	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓			Android 2.3.6 sw: S5570IXLXLD6	
233	Samsung S5690 Galaxy Xcover	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓			Android 2.3.6 sw: S5690XXLJ2	
234	Samsung S6500 Galaxy mini 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		Android 2.3.6 sw: S6500XXLK2	
235	Samsung S7220	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		S7220XXIB7
236	Samsung S7500 Galaxy Ace Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		Android 2.3.6 S7500XXLK1	
237	Samsung S7560 Galaxy Trend (Ace II X)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		Android 4.0.4 S7560XXAMF1	
238	Samsung S7580 Galaxy Trend Plus	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		Android 4.2.2 JDQ39.S7580XXUBOA1	
239	Samsung S7710 Galaxy Xcover 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓	✓				Android 4.1.2 sw: S7710XXAMB5	
240	Samsung S8000 Jet	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		S8000XXIF5	
241	Samsung S8300V	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		S8300BUIC6	
242	Samsung S8500 Wave	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		S8500XXLA1
243	Samsung S8530 Wave II	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		S8530XXJKA	
244	Samsung S8600 Wave 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		S8600XXLD1	
245	Samsung SGH-i900 OMNIA 8GB	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					i900XXIB2	
246	Samsung SGH-i900 OMNIA 16GB	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					i900BOHH2	
247	Samsung Xcover 271 (B2710)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		B2710BOLL1
248	SONY Xperia E (C1505)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		Android 4.1.1 sw 11.3.A.2.23	
249	SONY Xperia J (ST26i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		Android 4.1.2 sw 11.2.A.0.31	
250	SONY Xperia M (C1905)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		Android 4.3 sw 15.4.A.1.9	
251	SONY Xperia P (LT22i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		Android 4.1.2 sw 6.2.A.1.100	
252	SONY Xperia S (LT26)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01		Android 4.1.2 sw 6.2.B.1.96	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone

✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments	
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)		
253	SONY Xperia SP (C5303)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.2 sw 12.0.A.2.254	
254	SONY Xperia T (LT30p)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.1.2 sw 9.1.A.1.140	
255	SONY Xperia T2 Ultra (D5303)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.3 sw 19.1.1.A.0.165	
256	SONY Xperia Tipo (ST21i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.0.4 sw 11.0.A.22	
257	SONY Xperia U (ST25i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.0.4 sw 6.1.1.B.1.54	
258	SONY Xperia X Performance (F8131)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓									Android 7.1.1 sw 41.2.A.7.53
259	SONY Xperia XZ (F8331)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	07-0257-0F.01	Android 7.0 sw 39.2.A.0.417	
260	SONY Xperia XZ Premium (G8142)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	07-0257-0F.01	Android 7.1.1 sw 45.0.A.7.137	
261	SONY Xperia Z (C6603)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.2.2 sw 10.3.1.A.2.67	
262	SONY Xperia Z Ultra (C6833)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 4.4.4 sw 14.4.A.0.108
263	SONY Xperia Z1 (C6903)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 4.4.2 sw 14.3.A.0.757
264	SONY Xperia Z1 Compact (D5503)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.4.4 sw 14.4.A.0.118	
265	SONY Xperia Z2 (D6503)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 4.4.2 sw 17.1.A.2.55
266	SONY Xperia Z3 (D6603)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 5.0.2 sw 23.1.A.0.726	
267	SONY Xperia Z3+ (C6553)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 6.0.1 sw 32.2.A.0.305
268	SONY Xperia Z3 Compact (D5803)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 6.0.1 sw 23.5.A.1.291
269	SONY Xperia Z5 (E6653)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓					Android 6.0.1 sw 32.2.A.0.253
270	Sony Ericsson C902	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.05	R3EG004	
271	Sony Ericsson Elm	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.05	R7CA061	
272	Sony Ericsson J105i Naite	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.05	R1GA026	
273	Sony Ericsson K770i	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.05	R8BC004	
274	Sony Ericsson Satio (Idou)	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.05	R2AK006	
275	Sony Ericsson Vivaz	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	R2EA023	
276	Sony Ericsson W610i	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	0-07-0258-0.01	R6BC002	
277	Sony Ericsson W890i	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	R1FA035	
278	Sony Ericsson Xperia active (ST17)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.0.4 sw 4.1.B.0.587	
279	Sony Ericsson Xperia Arc (LT15i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.0.4 sw 4.1.B.0.587	
280	Sony Ericsson Xperia Arc S (LT18i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.01	Android 4.0.4 sw 4.1.B.0.587	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone
✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.

Compatibility list CC 9056 Plus

Updated: 2019-10-14 / V. 58
Device software version: BOX SW 309

No	Type	Display			Bluetooth connection to the last connected phone after ignition is switched on	Activation Bluetooth connection with device key	Phone's REDIAL activation	Possibility to switch car kit/private mode with Bluetooth device/phones keys	Multiparty call					Call lists			Phone book entries		Messages			A2DP supported	Access to mobile phone voice-dial function (voice tags)	Charger		Version of phone software used to test/ Comments
		Battery charge level	GSM-signal strength	Service provider					hold on 1 call	accept / reject waiting call	Swap between calls	merge to conference	init outgoing call during active call	Received calls	Missed calls	Dialled numbers	SIM Card	Phone	Download SMS	Receive new SMS / Popup	E-mail read Function			Charger available	Article code (Charger)	
281	Sony Ericsson Xperia neo V (MT11i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓		✓	0-07-0258-0.01	Android 4.0.4 sw 4.1.B.0.587
282	Sony Ericsson Xperia ray	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓		✓	0-07-0258-0.01	Android 4.0.4 sw 4.1.B.0.587
283	Sony Ericsson Xperia X1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓				✓		✓	0-07-0258-0.02	ROM ver1.05.111.13 R3AA013
284	Sony Ericsson Xperia X8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓		✓	0-07-0258-0.01	Android 2.1-update1 2.1.1.C.0.0
285	Sony Ericsson Xperia X10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓		✓	0-07-0258-0.01	Android 2.3.3 3.0.1.G.0.75
286	Sony Ericsson Xperia X10 mini (E10i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓		✓	0-07-0258-0.01	Android 2.1-update1 2.1.1.C.0.0
287	Sony Ericsson Xperia X10 mini pro (U20i)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓		✓				✓		✓	0-07-0258-0.01	Android 2.1-update1 2.1.1.A.0.6
288	Xiaomi Mi 4 LTE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	0-07-0258-0.01	
289	Xiaomi Mi 5	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓	✓	✓	✓	✓						✓	07-0257-0F.01	

BURY GmbH & Co. KG, Robert-Koch-Str.1-7, D-32584 Löhne, Hotline: (0) 180-6-842 468*, Faxline: (0) 180-6-842 329* *(20ct/call),
E-Mail: infoline@bury.com, Internet: www.bury.com

✓ working
✓¹ only from phone

✓² Mail function only from phone available with installed Applet for BlackBerry (Email Read Patch)
<http://bury.com/blackberrypatch/>

The scope of the functions described for all BURY products may vary according to your mobile phone, your network service provider and the date of your software. Subject to alterations and errors excepted.